

Town of Walton Streambank Stabilization at Beers Brook Site D
Before and After Photos



Photo 1: Looking downstream at left streambank erosion from Beers Brook Road.



Photo 2: Looking downstream after construction at rock rip rap along the left toe of streambank.

Town of Walton Streambank Stabilization at Beers Brook Site D
Before and After Photos



Photo 3: Looking downstream at left streambank erosion.



Photo 4: Looking downstream after construction at hardened riffle and rip rap along the toe of left streambank