

EWP Streambank Protection at Baxter Brook Project Site
Before and After



Photo 1: Looking upstream from right streambank at culvert outfall and failing head walls.



Photo 2: Looking upstream from right streambank at culvert headwall and plunge pool.

EWP Streambank Protection at Baxter Brook Project Site
Before and After



Photo 3: Looking downstream from left streambank at the streambed that has been downcutted.



Photo 4: Looking downstream from left streambank after construction of step pool structures.

EWP Streambank Protection at Baxter Brook Project Site
Before and After



Photo 5: Looking downstream from Baxter Brook Road at plunge pool and step pools.



Photo 6: Looking upstream from bottom of project at step pools and culvert outlet protection.